

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road standing near Hwy 12. Gravel has been applied and compacted to the surface to prevent vehicle tracking..

Inspection Photos



Photo 2. A culvert was installed to direct stormwater away from the access road and highway.

Inspection Photos



Photo 3. Facing northwest along the access road. A culvert was installed to prevent stormwater from flowing across the road.

Inspection Photos



Photo 4. The culvert was installed with rock rip/rap outlet protection.

Inspection Photos



Photo 5. The side of the access road has been filled in where it was eroded. Some rock rip/rap has been placed to prevent erosion.

Inspection Photos



Photo 6. Facing north along the access road. Gravel material has been applied to areas along the road.

Inspection Photos



Photo 7. Facing southeast at the location toward the cut slope. The cut slope is temporarily stabilized with hydro-mulch.