

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2017

Submitted Date:

11/02/2017

Document Number:

689900307**FIELD INSPECTION FORM**

Loc ID 309162 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Edie Fitzgerald		ediefitzgerald@tcenergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289043	WELL	PR	05/09/2008	GW	071-09185	GOLDEN EAGLE 20-13	RI

General Comment:This is a Follow Up Stormwater Management Inspection.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			
		Ditches	Pass			
		Culverts	Pass			
Hydro Mulch	Pass					Location cut slope BMP's

Comment: BMP's have adequately been installed and repaired. Culverts were installed to direct stormwater flow away from the access road and highway. Gravel was applied to the road surface and compacted to prevent vehicle tracking. The areas of erosion along the road were filled in with gravel material and some rock rip/rap to prevent erosion. The ditches along the road were cleaned out to direct stormwater flow. The cut slope at the location was hydromulched. See Attached Photos

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900308	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291892