



Photo 1. View of tank area west of the working area for the well. Small pieces of debris is present.





Photo 2. View of the southern edge of the working area facing eastward.





Photo 3. View of the project area from the northeastern corner facing center. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*).





Photo 4. View of silt trap in the southern portion of the project area that appears to recently have been maintained.



Photo 5. View of another silt trap at the southwestern edge of the project area, appears to be functioning.