

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2017

Submitted Date:

11/02/2017

Document Number:

674901960**FIELD INSPECTION FORM**
 Loc ID 322092 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Seale, Rod		rseale@djsimmons.com	<a href="#">Pet. Eng./Operations Mgr</a>
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	<a href="#">Durango</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208940	WELL	SI	01/01/2017	GW	033-06045	SQUAW CANYON-FEDERAL 2	EI

**General Comment:**

On October 31, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the DJ Simmons Squaw Canyon Federal #2. For the most recent field inspection report of this facility, please refer to document #685303951. COGCC SW Field Inspector Cal St. John and DJ Simmons representative Monty Reisenhoover were on site during this field inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Location sign mounted to meter shack.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Location looks like it was recently dragged.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Three strand barbed wire fencing around perimeter of location. Cattle guard at entrance is filled in with sediment.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Deadman # & Marked	# 4			corrective date
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.645650,-108.990289

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		37.645650,-108.990289

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		37.645341,-108.990294

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Inspector Name: Hughes, Jim

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	208940	Type:	WELL	API Number:	033-06045	Status:	SI	Insp. Status:	EI

--

Environmental		
<b>Spill/Remediation:</b>		
Comment:	Operator's representative indicated that samples of impacted area noted in inspection document #685303739 had been sent to Envirotech for analysis.	
Corrective Action:	Submit analytical results upon receipt to COGCC SW EPS.	Date: 12/04/2017
Emission Control Burner (ECB): _____		
Comment:	_____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass	Material Handling And Spill Prevention	Pass	Drip pot at tank load out lines.
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot for meter house drain line.

Comment: Well is currently shut in. Monitor meter house drain sump fluid levels.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On October 31, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the DJ Simmons Squaw Canyon Federal #2. For the most recent field inspection report of this facility, please refer to document #685303951. COGCC SW Field Inspector Cal St. John and DJ Simmons representative Monty Reisenhoover were on site during this field inspection.</p> <p>During this inspection it was noted that:</p> <p>An approximately 12" steel pipe with a lid was observed near the meter house. This pipe has oil in it from a drain line in the meter house. The operator's representative reported that the pipe has a bottom and is not open ended. The well is currently shut in and fluids are manually drained during routine maintenance.</p> <p>The secondary containment berms for the ASTs have recently been rebuilt according to the operator. Drip pots were noted on load out lines in both tank areas.</p> <p>The operator's representative indicated that samples of stained soil had been sent to Envirotech for lab analysis. Sample results shall be submitted to COGCC SW EPS upon receipt.</p>	hughesj	11/02/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901961	Inspection Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292376">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292376</a>