

Photo log for Response to October 5, 2017 Inspection

Document 689300253

COGCC conducted an inspection of the Schank J location (Location ID 336706) on October 5, 2017 (Document 689300253). During that inspection, COGCC made the following observations:

Weeds: Actively growing weeds on location, need to be controlled. Comply with Rule 603.f.

Stormwater: Location is washing out northeast of tank battery and running along east side of tank battery, discharging at southeast edge of location. Sediment is carrying off into field. Location is also starting to wash out between tank battery and separators. Install or repair required BMPs per Rule 1002.f

Response: Noble has mowed the weeds at the site. Noble has also repaired the erosion and installed new BMPs.

Name: Schank J

Location ID: 336706

COGCC conducted an inspection of the Schank J location (Location ID 336706) on October 5, 2017 (Document 689300253). During that inspection, COGCC made the following observations:

Stormwater: Location is washing out northeast of tank battery and running along east side of tank battery, discharging at southeast edge of location. Sediment is carrying off into field. Location is also starting to wash out between tank battery and separators.

COGCC – 10/5/17



Photo 5: Location washing out from northeast edge of tank battery and running along the east side of tank battery, discharging sediment off of location

Noble Energy – 10/12/17



Photo NBL1. Discharged sediment was recovered. The rills were repaired and new BMPs (check dams) were installed. Noble also installed rip rap in the corner of the pad to prevent future sediment loss.

Name: Schank J

Location ID: 336706

COGCC conducted an inspection of the Schank J location (Location ID 336706) on October 5, 2017 (Document 689300253). During that inspection, COGCC made the following observations:

Actively growing weeds on location, need to be controlled.

COGCC – 10/5/17



Photo 6: Actively growing weeds on location need to be controlled

Noble Energy – 10/12/17



Photo NBL2. The weeds have been mowed and the site has been graded.

Name: Schank J

Location ID: 336706

COGCC conducted an inspection of the Schank J location (Location ID 336706) on October 5, 2017 (Document 689300253). During that inspection, COGCC made the following observations:

Stormwater: Location is washing out northeast of tank battery and running along east side of tank battery, discharging at southeast edge of location. Sediment is carrying off into field. Location is also starting to wash out between tank battery and separators.

Actively growing weeds on location, need to be controlled.

Space left intentionally blank.

Noble Energy – 10/12/17



Photo NBL3. This is an additional photo that does not correspond to a COGCC inspection photo. This photo further illustrates that the weeds were mowed and the site was graded.