

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2017

Submitted Date:

11/03/2017

Document Number:

689400584

FIELD INSPECTION FORM

Loc ID 440803 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
SG Interests		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438645	WELL	PR	12/13/2015	LO	051-06045	Falcon Seaboard 11-90-12 3	PR
441412	WELL	WO	08/23/2015	LO	051-06139	Falcon Seaboard 11-90-12 5	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. Well permits set to expire in 2019.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	No capacity listed on produced water tanks. Reference Inspection Doc#674901953 for original corrective actions and dates.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs do not have placards and are not labeled. No capacity listed. Reference Inspection Doc#674901953 for original corrective actions and dates.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text" value="(866) 261-9766"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris in stormwater ditch on edge of location. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/09/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		500 BBLs	STEEL AST		
Comment:	52 frack tanks on location. 18 Connected with manifold. Hatches open on tanks at time of inspection. Flowback operations in process.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Location appears to have sufficient down gradient perimeter berms for stored and flowback tanks.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	4		HEATED STEEL AST		,		
Comment:		See sign section of inspection.					
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 438645 Type: WELL API Number: 051-06045 Status: PR Insp. Status: PR

Facility ID: 441412 Type: WELL API Number: 051-06139 Status: WO Insp. Status: PR

Producing Well

Comment: Flowing

Corrective Action:

Date:

Workover

Comment: • FLOWBACK: MVCI Services. Flowing apprx. 20bbls/ hour produced water. Stored in tanks before transferring in poly line.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Debris in stomwater ditch. See housekeeping section of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400585	Falcon Seaboard 11-90-12	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292980