

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2017

Submitted Date:

11/03/2017

Document Number:

689400588

**FIELD INSPECTION FORM**

Loc ID 311729 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 77330  
Name of Operator: SG INTERESTS I LTD  
Address: 100 WAUGH DR SUITE 400  
City: HOUSTON State: TX Zip: 77007

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Ash, Margaret		margaret.ash@state.co.us	
SG Interests		inspection@sginterests.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283607	WELL	PR	07/01/2014	GW	051-06070	FALCON SEABOARD 11-90-12 #1A	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	(866) 261-9766		
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Chemical container		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Other	# 1		
Comment:	Chemical container		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 283607 Type: WELL API Number: 051-06070 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400589	Falcon Seaboard 11-90-12 #1A	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4293092</a>