



Photo 1. View of area recently reclaimed around pipeline riser. Area is recently reclaimed.





Photo 2. View of area west of repaired riser. This area is reclaimed with straw blanket and fencing.



Photo 3. View of area south of repaired riser that was recently reclaimed. Area is surface roughened and appears to be seeded.