

- Federal 2 - 19
- 05-033-06071



Photo 1: Wellhead sign. Previous inspection.

- Federal 2 - 19
- 05-033-06071



Photo 2: Wellhead sign. Follow-up inspection.

- Federal 2 - 19
- 05-033-06071



**Photo 3: Wellhead and riser. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 4: Wellhead. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 5: Flowline riser at meter house open to atmosphere. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 6: Removed riser at meter house. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 7: (4) risers off backside of gas meter run shed. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 8: Removed risers off backside of gas meter run. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 9: Riser in production tank battery. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 10: Removed riser at tank battery. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 11: Burnt batteries under solar panel. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 12: Removed batteries and solar panel. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 13: Deteriorated bag of material inside separator box. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 14: Cleaned up and removed material from separator. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



Photo 15: Unlabeled 210 BBL steel tank. Previous inspection.

- Federal 2 - 19
- 05-033-06071



Photo 16: Labeled 210 BBL tank. Follow-up inspection.

- Federal 2 - 19
- 05-033-06071



**Photo 17: Thistle and weeds growing on location. Previous inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 18: Cleaned up and mowed location overview. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 19: Location overview from entry point. Follow-up inspection.**

- Federal 2 - 19
- 05-033-06071



**Photo 20: Recently turned land farm area. Follow-up inspection.**