

- Federal #1 - 19
- 05-033-06060



Photo 1: Wellhead sign. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 2: Wellhead sign. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 3: Wellhead with impacted soil around base of wellhead and 1" steel riser. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 4: Cleaned up impacted soil and removed riser. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 5: Risers (5) beside gas meter shed. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 6: Removed risers by meter run shed. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 7: Risers (6) outside separator fencing. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 8: Removed risers outside separator fencing. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 9: Risers (3) outside separator fencing out from first set of (6). Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 10: Removed risers outside separator fencing. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 11: Risers inside production tank battery fencing. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 12: Removed risers inside tank battery fencing. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 13: Riser and heavy gauge wiring outside production tank fencing. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 14: Removed risers outside tank battery fencing. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 15: Water tank load out spill prevention full and impacted soil from overflow. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 16: Cleaned up area around water tank load out. Previous inspection.

- Federal #1 - 19
- 05-033-06060



Photo 17: Location overview. Follow-up inspection.

- Federal #1 - 19
- 05-033-06060



Photo 18: Location overview outside entry point. Follow-up inspection.