

- Cross Canyon Unit 1
- 05-033-06012



Photo 1: Wellhead sign. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 2: Wellhead sign. Follow-up inspection.

- Squaw Canyon - Federal 2
- 05-033-06045



Photo 3: Thistle. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 4: Removed steel cable and Thistle. Follow-up inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 5: Line into meter and low point stub up and valve. Previous inspection

- Cross Canyon Unit 1
- 05-033-06012



Photo 6: Line into meter and low point stub up with locked and tagged valve. Follow-up inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 7: Stormwater erosion channel off front of production tank berm. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 8: Repaired surface area and new berm. Follow-up inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 9: Stormwater flow coming down access road grade at entrance. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 10: New diversion berm for stormwater coming off access road. Follow-up inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 11: Erosion channel on SW corner beside carport shelter. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 12: New berm along perimeter to divert/control stormwater. Follow-up inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 13: Erosion channel on SW corner along separator berms. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 14: Repaired surface area and new berm to control stormwater. Follow-up inspection.