

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2017

Submitted Date:

11/06/2017

Document Number:

685303980**FIELD INSPECTION FORM**Loc ID 322090 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Findings:**11 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|-----------------------------|--|
| Brashea, Rod | | rbrashea@blm.gov | Fed Inspection Reports |
| Seale, Rodney | 505-326-3753 | rseale@djsimmons.com | SW Inspection Reports |
| Leonard, Mike | | mike.leonard@state.co.us | |
| Rabinowitz, Daniel | 970-385-1363 | drabinow@blm.gov | Durango |
| Telecky, Barbara | | btelecky@blm.gov | Durango |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 208908 | WELL | PR | 03/01/2017 | GW | 033-06012 | CROSS CANYON UNIT 1 | PR |

General Comment:[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | DEBRIS | | |
| Comment: | Steel cable - Corrective action completed. | | |
| Corrective Action: | | Date: | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Risers - Corrective action completed. | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | Corrective action completed. | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 208908 Type: WELL API Number: 033-06012 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Berms | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Berms around production tank. |
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Culverts | Pass | | | |
| Ditches | Pass | Ditches | Pass | | | |

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 685303993 | Inspection pictures. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295699 |