

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/06/2017

Submitted Date:

11/06/2017

Document Number:

684904679**FIELD INSPECTION FORM**
 Loc ID 440718 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10359Name of Operator: WARD PETROLEUM CORPORATIONAddress: 215 WEST OAK STREET #1000City: FORT COLLINS State: CO Zip: 80521**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hal, Marshall	970-3895487	marshall@wardpetroleum.com	
,		jeffd@wardpetroleum.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443366	WELL	DG	10/11/2017	LO	001-09858	Schaefer 2536-1-4HC	PR
443368	WELL	DG	10/11/2017	LO	001-09860	Schaefer 2413-3-15HN	PR
445283	TANK BATTERY	AC	04/11/2014		-	Schaefer 24-3-7HC	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tanks recently painted, currently unlabeled		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	barbed wire topped chain link		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	2 VRU, 1 sales		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	STEEL AST		39.944930,-104.834880	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	533bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	OTHER	STEEL AST		39.944930,-104.834880	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	533bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	YES		
--------	-----	--	--

Comment:	Currently in upset. PRVs on tank venting.		
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 443366	Type: WELL	API Number: 001-09858	Status: DG      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:			Date:
<b><u>Complaint</u></b>			
Comment:	<p>Complaint #: 200444609</p> <p>Field Inspector Assigned: C Pesicka</p> <p>Well Number: 05-      Location #: 440718</p> <p>Inspection Document #: 684904679</p> <p>Nature of complaint: Sound</p> <p>If Sound GPS Coordinates of Survey Location: 39.94315, -104.83527</p> <p>Inspection Observations:</p> <p>An inspection of the above location was conducted with focus sound. A sound study was conducted at the indicated location on 11/06/17 from 1215hr to 1315hr. The ambient temperature was 40 degrees Fahrenheit and wind speed was calm. The sound study resulted in an leqC of 69.9 dB, in excess of rule 802.d. The site is currently undergoing an upset condition. When working order is restored, will run another sound study and compare..</p>		
Corrective Action:			Date:
<b><u>BradenHead</u></b>			
Comment: Bradenhead plumbed to surface			
Corrective Action:			Date: _____
Facility ID: 443368	Type: WELL	API Number: 001-09860	Status: DG      Insp. Status: PR
<b><u>Producing Well</u></b>			
Comment: PR			
Corrective Action:			Date:
<b><u>BradenHead</u></b>			
Comment: Bradenhead plumbed to surface			
Corrective Action:			Date: _____
Facility ID: 445283	Type: TANK	API Number: -	Status: AC      Insp. Status: AC

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684904680	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295766</a>
684904681	Sound Survey results	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295767">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295767</a>