



Photo 1: View of cobble stormwater controls installed in the western portion of the project area.



Photo 2: Another view of stormwater controls within the western portion of the project area. Cobble check dams visible in background.



Photo 3: View of stormwater controls and erosion repair downstream from culvert outlet near the entrance of the well pad.



Photo 4: View of cobble run down and silt trap in the southeastern corner of the project area.



Photo 5: View of stormwater controls in the northeastern portion of the project area where stormwater flows eastward (toward the upper right-hand corner of the photo).



Photo 6: View of cobble stormwater controls in the northern portion of the project area, upstream of Photo 5.



Photo 7: View of the project area from the northeastern corner facing center. Cut slopes were recently seeded and hydromulched.



Photo 8: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 9: View of germination Transect 1, within the western portion of the project area. Area was recently seeded, and this study provides baseline data.



Photo 10: Birdseye view of typical quadrat along germination Transect 1.



Photo 11: View of germination Transect 2, within the western portion of the project area. Area was recently seeded, and this study provides baseline data.



Photo 12: Birdseye view of typical quadrat along germination Transect 2.