



Photo 1. View of approximate transect locations.



Photo 2. View of the beginning of Transect 1, facing northward, within the project disturbance.



Photo 3. Birdseye view of vegetation at the mid-point of Transect 1.





Photo 4. View of the end of Transect 1, facing southward.



Photo 5. View of the beginning of Transect 2, facing southward, within the project disturbance.



Photo 6. Birdseye view of vegetation at the mid-point of Transect 2.



Photo 7. View of the end of Transect 2, facing northward.





Photo 8. View of the beginning of Transect 3, facing northward, within the project disturbance.



Photo 9. Birdseye view of vegetation at the mid-point of Transect 3.



Photo 10. View of the beginning of Transect 4, facing southward, within the project disturbance.



Photo 11. Birdseye view of vegetation at the mid-point of Transect 4.



Photo 12. Birdseye view of spotted knapweed (*Centaurea stoebe*) rosettes within the project area.



Photo 13. Birdseye view of spotted knapweed (*Centaurea stoebe*) rosettes within the project area in October.



Photo 13. Birdseye view of yellow toadflax (*Linaria vulgaris*) within the southeastern portion of the project area.



Photo 15. View of leafy spurge (*Euphorbia esula*) within the southern portion of the project area in October.



Photo 16. View of pipeline marker south of well pad in foreground. Pipeline riser that needs removal is located where Margaret Ash is in background.



Photo 17. Closeup view of pipeline marker indicating owner of pipeline.



Photo 18. View of sediment deposition where sediment from the cut-slope is eroding into a swale in the southwestern corner of the project area.