

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2017

Submitted Date:

11/08/2017

Document Number:

689500344

FIELD INSPECTION FORM

Loc ID 314500 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Archuleta, Chris		carchuleta@chevron.com	Wilson Creek Field
Peterson, Diane	970-675-3842	dlpe@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228864	WELL	PR	02/15/1998	OW	103-05855	WILSON CREEK UNIT 57	PR

General Comment:

Well Pr via submersible electric pump - no leaks/venting at time of inspection. Well flows to centralized tank battery/separator

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:	Present/complete		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chem tote with secondart containment		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 228864 Type: WELL API Number: 103-05855 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Pr via submersible electric pump - no leaks/venting at time of inspection. Well flows to centralized tank battery/separator](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500345	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4297884