

Inspection Photos  
Well Name: ECK 12-90-1 1  
Location ID: 428197



**Photo 1. Wellhead.**



**Photo 2. Pipe racks still on location.**

Inspection Photos  
Well Name: ECK 12-90-1 1  
Location ID: 428197



Photo 3. Stored gravel. Cut slope erosion.




Photo 4. Update NFPA diamond for Produced Water or provide documentation for 0 fire hazard rating

Inspection Photos  
Well Name: ECK 12-90-1 1  
Location ID: 428197



**Photo 5. one of two culverts with silted in inlet.**



**Photo 6. Silted in inlet to culvert**