

Inspection Photos



Photo 1. Facing southeast along the access road. The access road has recently been graded and soil was pushed onto the road.

Inspection Photos



Photo 2. The soil pushed onto the road is loose and susceptible to erosion.

Inspection Photos



Photo 3. The arrow points to the side of the road cut where soil was pushed onto the road which is also causing the road to become widened. The grade of the road is being lowered by grading activities.

Inspection Photos



Photo 4. Facing southeast toward the location. The location was regraded. Some of the vegetation may have been disturbed.

Inspection Photos



Photo 5. The well sign at the location does not have an operator name.

Inspection Photos



Photo 6. There is List B noxious weeds (Bull thistle) noticed at the location.

Inspection Photos



Photo 7. Facing southeast toward the location. The location was regraded. Some of the vegetation may have been disturbed.