

Inspection Photos



Photo 1. Facing southwest along the access road. There is stormwater erosion occurring down the access road. No BMP's are installed to prevent erosion.

Inspection Photos



Photo 2. There are no BMP's installed along the access road. Stormwater erosion has incised the side of the road.

Inspection Photos



Photo 3. Facing northwest along the access road. A culvert was installed to prevent stormwater from flowing across the road.

Inspection Photos



Photo 4. Facing toward the northwest cut slope which is not stabilized. Stormwater erosion is occurring along the cut slope.

Inspection Photos



Photo 5. Facing north toward the cut slope. There is a ditch which has filled in with sediment at the base of the cut slope. The ditch divert stormwater toward the access road and southwest side of the location. No other BMP's are installed.

Inspection Photos



Photo 6. Facing toward the southwest side of the location. The ditch directs stormwater toward this direction however no other BMP's are installed to contain sediment and stormwater erosion.

Inspection Photos



Photo 7. There is a few List B noxious weeds (Musk thistle) noticed at the location.