

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2017

Submitted Date:

11/03/2017

Document Number:

689400584**FIELD INSPECTION FORM**
 Loc ID 440803 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
SG Interests		inspection@sginterests.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">NW Supervisor</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438645	WELL	PR	12/13/2015	LO	051-06045	Falcon Seaboard 11-90-12 3	PR
441412	WELL	WO	08/23/2015	LO	051-06139	Falcon Seaboard 11-90-12 5	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. Well permits set to expire in 2019.

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	ASTs do not have placards and are not labeled. No capacity listed. Reference Inspection Doc#674901953 for original corrective actions and dates.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No capacity listed on produced water tanks. Reference Inspection Doc#674901953 for original corrective actions and dates.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	(866) 261-9766	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris in stormwater ditch on edge of location. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/09/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: Reference Inspection Doc#674901953 for original corrective actions and dates.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		500 BBLS	STEEL AST		
Comment:	52 frack tanks on location. 18 Connected with manifold. Hatches open on tanks at time of inspection. Flowback operations in process.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Location appears to have sufficient down gradient perimeter berms for stored and flowback tanks.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4		HEATED STEEL AST		,	
Comment:		See sign section of inspection.				
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**Facility ID: 438645 Type: WELL API Number: 051-06045 Status: PR Insp. Status: PRFacility ID: 441412 Type: WELL API Number: 051-06139 Status: WO Insp. Status: PR**Producing Well**Comment: Flowing

Corrective Action:

Date:

**Workover**Comment: • FLOWBACK: MSCI Services. Flowing apprx. 20bbls/ hour produced water. Stored in tanks before transferring in poly line.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Debris in stormwater ditch. See housekeeping section of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401449497	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292982">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292982</a>
689400585	Falcon Seaboard 11-90-12	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292980">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4292980</a>