

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2017

Submitted Date:

11/10/2017

Document Number:

678301180**FIELD INSPECTION FORM**Loc ID 317978 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Anadarko		COGCCinspections@Anadarko.com	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240296	WELL	SI	05/01/2017	GW	123-08084	LEONARD ABBETT GAS UNIT 1	EI
446400	TANK BATTERY	AC	06/28/2016		-	LEONARD ABBETT GAS UNIT-63N67W 23SWNE	EI
452969	SPILL OR RELEASE	AC			-	Abbett Leonard GU 1	EI

**General Comment:**

multi-well battery remains at site. battery lies within 100yr flood plain. crude and PW tanks are anchored appropriately. metal berms used around tanks

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: no surface spills noted, subsurface spill near well bore (452969) discovered during P&A of well and reported by operator.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	#		
Comment:	numerous flowlines listed as in place but not abandoned with wells abandoned including flowlines from Abbett Leonard GU 1, HSR Abbett 1-23A, HSR Abbett 2-23, HSR Abbett 8-23 to this battery. Unused flowlines are considered unused equipment at location. see attached photos of signs indicating flowlines in place		
Corrective Action:	Comply with Rule 603.f .		Date: 12/11/2017
Type: Horizontal Heated Separator	# 2		
Comment:	earthen berms		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 240296 Type: WELL API Number: 123-08084 Status: SI Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: well has recently been P&A

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 446400 Type: TANK API Number: - Status: AC Insp. Status: EIFacility ID: 452969 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678301181	sign 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4299147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4299147</a>
678301182	sign 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4299148">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4299148</a>