

COGCC conducted an inspection of the Lilli Unit 2-8 location (Location ID 326772) on September 26, 2017 (Document 684904467). During that inspection, COGCC made the following observations:

Tanks and Berms: Berms – Berms are low in places. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Stormwater: Stormwater erosion in center of site, eroding to the east. Install or repair required BMPs per Rule 1002.f.

Response: Noble has repaired the berms and erosion on-site.

Name: Lilli Unit 2-8
Location ID: 326772

COGCC conducted an inspection of the Lilli Unit 2-8 location (Location ID 326772) on September 26, 2017 (Document 684904467). During that inspection, COGCC made the following observations:

- Tanks and Berms: Berms – Berms are low in places. Repair or install berms or other secondary containment devices per Rule 605.a.(4).
- Stormwater: Stormwater erosion in center of site, eroding to the east. Install or repair required BMPs per Rule 1002.f.

COGCC – 9/26/17



Photo 1: Location, looking NE

Noble Energy – 10/10/17



Photo NBL1. Erosion and berms have been repaired

Name Lilli Unit 2-8

Location ID: 326772

COGCC conducted an inspection of the Lilli Unit 2-8 location (Location ID 326772) on September 26, 2017 (Document 684904467). During that inspection, COGCC made the following observations:

Tanks and Berms: Berms – Berms are low in places. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

COGCC – 9/26/17



Photo 3: Low berms at tank battery

Noble Energy – 10/10/17



Photo NBL2. The berms of the containment have been enlarged and compacted.

Name: Lilli Unit 2-8
Location ID: 326772

COGCC conducted an inspection of the Lilli Unit 2-8 location (Location ID 326772) on September 26, 2017 (Document 684904467). During that inspection, COGCC made the following observations:

Stormwater: Stormwater erosion in center of site, eroding to the east. Install or repair required BMPs per Rule 1002.f.

COGCC – 9/26/17



Photo 5: Stormwater erosion at location, between treater and battery.

Noble Energy – 10/10/17



Photo NBL3. The erosion has been repaired by filling and grading.