

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/09/2017

Submitted Date:

11/14/2017

Document Number:

674901962**FIELD INSPECTION FORM**

Loc ID 311903 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
St John, William (Cal)		cal.stjohn@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		inspections@catamountep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216303	WELL	PR	01/24/1994	GW	067-07909	SEMLER GAS UNIT 1	EI
452581	SPILL OR RELEASE	AC	11/09/2017		-	WATER TANK	EI

**General Comment:**

On November 9, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Semler GU #1. For the most recent field inspection report for this facility, please refer to document #680601910. This site visit was in response to Spill/Release Point ID #452581.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Tanks have placards and have contents and capacity labelled.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign near well head.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information posted on location sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Other	Pump Jack	<= 1 bbl		
Comment:	Stained soil observed near muffler exhaust. Issue was noted on inspection document #685303044 and has either not been addressed or has reoccurred.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.			Date: 12/13/2017
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Chain link fencing around pump jack and well head.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:

Type: Prime Mover	# 1	
Comment:	Natural gas powered.	
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		37.099738,-107.718897
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Adequate
Comment:	Spill/Release Point ID #452581 reportedly left the containment area. Inadequate berm around tanks.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.4.			Date: 12/13/2017

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216303	Type:	WELL	API Number:	067-07909	Status:	PR	Insp. Status:	EI
Facility ID:	452581	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Ditches	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 9, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Semler GU #1. For the most recent field inspection report for this facility, please refer to document #680601910. This site visit was in response to Spill/Release Point ID #452581. Stained soil observed near muffler exhaust. Issue was noted on inspection document #685303044 and has either not been addressed or has reoccurred. A hand built earthen dam was observed near the terminus of the produced water release.	hughesj	11/14/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901963	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4300926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4300926</a>