



Photo 1. View from the northeastern corner facing center.





Photo 2. View of the northern portion of the project area facing westward. Revegetation is progressing, largely with grasses. Vegetation is grazed and not in identifiable form. Grazing should be monitored as livestock exclusion may be needed.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of erosional channels forming near the well pad entrance. Stormwater controls need to be installed to stabilize erosion in eroding areas.



Photo 5. View of erosional channels in the southwestern portion of the project area.