



Photo 1. View from the southeastern corner of the project area facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. What appears to be surface owner equipment as well as some unused oil and gas related equipment is stored in the project area.



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of Russian knapweed (*Acroptilon repens*) growing within the southern portion of the project area. Approximately 150 individuals observed.



Photo 5. View of the project area from the southwestern corner facing center.