

**Inspection Photos**  
**Location Name: Ditorro, John #1-A**  
**API: 05-123-09622**



**Photo 1: Location, looking SE**



**Photo 2: Wellhead, looking W**

Inspection Photos  
Location Name: Ditorro, John #1-A  
API: 05-123-09622



Photo from prior inspection for comparison



Photo 3: Stained soil wellhead

**Inspection Photos**  
**Location Name: Ditorro, John #1-A**  
**API: 05-123-09622**



**Photo from prior inspection for comparison**



**Photo 4: Weeds controlled**

Inspection Photos  
Location Name: Ditorro, John #1-A  
API: 05-123-09622



Photo from prior inspection for comparison



Photo 5: Weeds controlled

Inspection Photos  
Location Name: Ditorro, John #1-A  
API: 05-123-09622



Photo from prior inspection for comparison



Photo 6: Stained soil removed, some impacted soil remaining

Inspection Photos  
Location Name: Ditorro, John #1-A  
API: 05-123-09622



Photo from prior inspection for comparison



Photo 7: Stained soil in separator house removed

Inspection Photos  
Location Name: Ditorro, John #1-A  
API: 05-123-09622



Photo from prior inspection for comparison



Photo 8: Stained soil at ECD removed