

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2017

Submitted Date:

11/15/2017

Document Number:

684904704**FIELD INSPECTION FORM**

Loc ID 452048 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1001 17TH STREET #1250City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Dickinson, Mike		mdickinson@confluencelp.com	SR VP of Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452352	WELL	DG	11/01/2017		123-45542	Buford 33-10-4L	DG

General Comment:

Inspected FacilitiesFacility ID: 452352 Type: WELL API Number: 123-45542 Status: DG Insp. Status: DG**Complaint**Comment: [Complaint #: 200444626](#)[Field Inspector Assigned: C Pesicka](#)[Well Number: 05- Location #: 440718](#)[Inspection Document #: 684904704](#)[Nature of complaint: Sound](#)[If Sound GPS Coordinates of Survey Location: n/a](#)[Inspection Observations:](#)

[Went to location to conduct sound study but wind was ~5 mph per anemometer, and increasing. Spoke with company man on site. Third party was going to come out to site to do a mitigation study and determine what the operator needs to do. Will attempt sound study when conditions improve.](#)

Corrective Action:

Date: