

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2017

Submitted Date:

11/16/2017

Document Number:

690300115

**FIELD INSPECTION FORM**

Loc ID 442505 Inspector Name: Spencer, Stan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10500  
Name of Operator: COACHMAN ENERGY OPERATING COMPANY LLC  
Address: 1125 17TH STREET SUITE 410  
City: DENVER State: CO Zip: 80202

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Granahan, Kyle		kyle.granahan@state.co.us	
Mut, Neyeska	303-296-3535	neyeska@cynosure-energy.com	
Lujan, Carlos		carlos.lujan@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**General Comment:**

Site inspection w Alex Fischer, COGCC prior to pit closure. Pit is a non permitted drilling pit. A Form 15 Pit Permit for drilling pit using bentonitic mud is not required per Rule 903 c. Observation of the pit does not reveal indications of a petroleum release such as staining or odors, therefore a Form 27 remediation plan is not required. Pit appears to have been excavated by heavy equipment and large soil volumes are stockpiled adjacent to the pit and around the location. Sample data indicated that only arsenic exceeded Table 910-1 but concentrations appear to be within background levels. Well is shut in. Weeds encroaching on wellhead. No meter in meter shed.

Submit F-4 Sundry with analytical data and retain information in operator records. Proceed with backfilling pit and interim reclamation per BLM requirements.