

Inspection Photos
Location Name: Moore 13-35
API #: 05-123-19455
Location ID: 330681



Northeast edge of location erosion has been repaired



Wellhead looking south. 1" steel riser has been LOTO and labeled