

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401463032

Date Received:

11/17/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

-

sandridgeenvironmental@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102328

Inspection Date: 10/24/2017

FIR Submit Date: 10/29/2017

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: _____

Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057- -00 Facility ID: 447512

Facility Name: Open Range Number: 18

Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 CA# 108374

Corrective Action: Remove the weeds (Debris) referenced above from location. Develop & implement weed control Plan for the Annual Non Noxious as well as Noxious Weeds in Spring of 2018

Date: 11/27/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: Pad is still under construction; however, weeds will be removed during construction. An IPM plan has been developed for the field and control measures will be resumed in growing season of 2018.

COGCC Decision: _____

COGCC
Representative:

2 CA# 108375

Corrective Action: Repair disturbed area, installing BMPs needed for perimeter controls. it should be determined who (Pipe line Co / Operator ?) caused rutting off Location and have disturbance addressed.

Date: 11/13/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: Disturbance was created during staging of material for pipeline construction. The pipeline is currently being constructed and all disturbed area will be reclaimed, and the seedbed will be prepared for seeding operations in Spring 2018.

COGCC Decision: _____

COGCC
Representative:

3 CA# 108376

Corrective Action: Repair road, installing BMPs to address erosion issues. Refer to Photos attached

Date: 11/27/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: Pad construction is still ongoing and the referenced area is located within erosion control.

COGCC Decision: _____

COGCC
Representative:

4 CA# 108377

Corrective Action: Maintain /Repair Silt fence or remove if other BMP is installed as perimeter Control.

Date: 11/27/2017

Response: CA COMPLETED

Date of Completion: 11/09/2017

Operator Comment: New silt fence has been installed around the perimeter of the site.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed: _____

Title: EH&S Specialist

Date: 11/17/2017 11:06:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401463036	New silt fence install.

Total Attach: 1 Files