

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2017

Submitted Date:

11/17/2017

Document Number:

674901970**FIELD INSPECTION FORM**

Loc ID 445811 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
 Name of Operator: KINDER MORGAN CO2 CO LP
 Address: 1001 LOUISIANA ST SUITE 1000
 City: HOUSTON State: TX Zip: 77002

Findings:

- 8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Millican, Chris	970-882-5504	chris_millican@kindermorgan.com	SW Inspection Reports
Hannigan, Mike	970-882-5532	michael_hannigan@kindermorgan.com	
Swift, Barry	970-882-5545	barry_swift@kindermorgan.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445810	WELL	PR		LO	033-06181	DC 29	EI

General Comment:

On November 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan DC #29. For the most recent field inspection report of this facility, please refer to document #685303754. This site visit was in response to complaint #200444589.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Operator contact information posted on location sign.		
Corrective Action:		Date:	

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around well head.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 445810 Type: WELL API Number: 033-06181 Status: PR Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
	Piles	Adequate	37.746350	-108.829847
Comment	Soil and gravel stored on lined secondary containment device with cover. Material was sampled for waste characterization on 11/16/17 prior to disposal at a landfill.			
Corrective Action				Date: _____

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Sediment Traps	Pass			
Sediment Traps	Pass					
Gravel	Pass	Compaction	Pass			
Slope Roughening	Pass	Ditches	Pass			
Compaction	Pass	Check Dams	Pass			
Waddles	Pass	Gravel	Pass			
Check Dams	Pass					
Drains	Pass	Rip Rap	Pass			
Ditches	Pass					
Mulching	Pass					
Gradient Terraces	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On November 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan DC #29. For the most recent field inspection report of this facility, please refer to document #685303754. This site visit was in response to complaint #200444589.</p> <p>The stock panel fencing around the wellhead has rust colored streaks on it. No other staining was noted during this inspection.</p> <p>Kinder Morgan pipeline crews were on location making preparations for tying in the well. Welders were assembling test heads as well as the stainless steel gathering line.</p> <p>A temporary containment area of approximately 20' by 45' was observed in the SE corner of the location. This material is reportedly awaiting waste characterization results prior to disposal.</p>	hughesj	11/17/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901971	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305055