

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2017

Submitted Date:

11/17/2017

Document Number:

674901972**FIELD INSPECTION FORM**Loc ID 313482 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Garrigues, Robert		rgarrigues@blm.gov	Tres Rios

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112977	PIT	AC			-	SCHMIDT 2	EI
224191	WELL	PR	11/30/2007	GW	083-06256	SCHMIDT 2	EI
452931	SPILL OR RELEASE	AC			-	Schmidt #2 Condensate Pit	EI

General Comment:

On November 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Schmidt #2. For the most recent field inspection report for this facility, please refer to document #685301849. This site visit was in response to Spill/Release Point ID #452931.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Pit liner material, netting, and netting supports stored on location.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/18/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe protective barrier around well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 2		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Combuster		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 112977 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 224191 Type: WELL API Number: 083-06256 Status: PR Insp. Status: EIFacility ID: 452931 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Lined: Pit ID: 112977 Lat: 37.364793 Long: -108.787530Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Liner has been removed for excavation.Corrective Action Date: g**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Netting and supports have been removed for excavation.Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
On November 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Schmidt #2. For the most recent field inspection report for this facility, please refer to document #685301849. This site visit was in response to Spill/Release Point ID #452931. The netting and liner have been removed from Pit Facility ID #112977. An excavated area approximately 50' by 60' by 6' with stained soils was observed during this field inspection. Please refer to document #401450235 for information regarding this release.	hughesj	11/17/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901973	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305194