



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of tank area in north of the well pad.



Photo 4. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing and largely comprised of western wheatgrass (*Pascopyrum smithii*), gambel oak (*Quercus gambelii*), and dropseed (*Sporobolus sp.*).



Photo 5. View of erosional channel forming in the southern portion of the project area, approximate 18 inches wide and 10 inches deep.



Photo 6. View of another erosional channel forming in the southern portion of the project area.