

Inspection Photos
Location Name: Ruebel et al 1-2
API: 05-001-08664



Wellhead



Battery

Inspection Photos
Location Name: Ruebel et al 1-2
API: 05-001-08664



Separator & Meter Run



Produced Water Vault, **Corrective Action: Water vault access bent open.**

Inspection Photos
Location Name: Ruebel et al 1-2
API: 05-001-08664



Lease Road, Corrective Action: Overgrown weeds on road from facility to wellhead.



Wellhead detail, Corrective Action: Packing in master valve appears to be leaking causing stained soil.