

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2017

Submitted Date:

11/18/2017

Document Number:

680102364**FIELD INSPECTION FORM**

Loc ID 314846 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Haub, Mike		MHaub@chevron.com	Reclamation Insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229737	WELL	PA	08/30/2008	GW	103-07394	WILSON CREEK UNIT 62	RI

General Comment:

2017 Flowline NTO Inspection 1000' Buffer (or statewide). There is No visual evidence of equipment on location. No indication of other facilities identified with aerial imagery assessment.

Well was Plugged & Abandoned 8/30/2008. This is a Federal mineral Federal surface location therefore COGCC will not be releasing the final surface reclamation. Photos are attached.

Inspected FacilitiesFacility ID: 229737 Type: WELL API Number: 103-07394 Status: PA Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102396	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305719