

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2017

Submitted Date:

11/18/2017

Document Number:

680102365**FIELD INSPECTION FORM**

Loc ID 314499 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Haub, Mike		MHaub@chevron.com	Reclamation Insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228863	WELL	PA	09/11/2008	ERIW	103-05854	WILSON CREEK UNIT (MR-SN) 36-WD	RI

General Comment:

2017 Flowline NTO Inspection 1000' Buffer (or statewide). There is No visual evidence of equipment on location. No indication of other facilities identified with aerial imagery assessment.

Well was Plugged & Abandoned 9/11/2008. This is a Federal mineral Federal surface location therefore COGCCC will not be releasing the final surface reclamation. Photos attached

Inspected Facilities

Facility ID: 228863 Type: WELL API Number: 103-05854 Status: PA Insp. Status: RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102397	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305720