

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2017

Submitted Date:

11/20/2017

Document Number:

690100240**FIELD INSPECTION FORM**

Loc ID 330347 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		cogccinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251132	WELL	PR	08/05/2002	GW	123-18935	HSR-ACORD 13-29	EG

**General Comment:**

Engineering Integrity Inspection performed on November 15th, 2017 in response to initial form 19 spill report Doc #401455341 received by COGCC on 11/13/2017 that outlines: While removing the HSR-Acord 13-29 flowline, historical petroleum hydrocarbon impacts were encountered. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

**Inspected Facilities**

Facility ID: 251132 Type: WELL API Number: 123-18935 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well site flowline appears to be abandoned in place; area on and around location backfilled and re-graded. As outlined in the corrective actions section of supplemental form 19 doc #401455341: While removing the HSR-Acord 13-29 flowline, historical petroleum hydrocarbon impacts were encountered. The volume of the release is unknown. The flowline was removed and the excavation was backfilled and restored to its pre-release grade.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Notice of flowlines abandoned doc #401333305 received by COGCC on 07/06/2017; Form 6 intenet to abandon doc #401301419 received on 06/06/2017.	maclarej	11/20/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100241	Flowline removed; Area recontoured (view North)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4306094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4306094</a>
690100242	Flowline removed; Area recontoured (view South)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4306095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4306095</a>