

# Interim Reclamation and Stormwater Inspection

November 15, 2017

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 450197

Weld County, CO

NESE Section 26 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 1.** Photo taken from the entrance of location, facing North. Tracking pad devices installed at location.



**Photo 2.** Photo taken from the southeastern location, facing East. Ditch BMP installed around the perimeter of the location. Ditch depth appeared shallow along portions. Stockpile has been constructed to a significant height and may need additional stabilization as rill erosion was observed along portions of the stockpile.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 3.** Photo taken from the eastern location, facing South. Check dam BMP installed along portions of the eastern ditch BMP. See comments under Photo 2.



**Photo 4.** Photo taken from the northern location, facing West. Sediment basin has been installed with a stabilized outlet.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 5.** Photo taken from the northern location, facing Northwest. Silt fence BMP constructed around the stabilized outlet area of the sediment basin.



**Photo 6.** Photo taken from the northern location, facing South. Rip-rap and S-Fence have been installed for the stabilized outlet area.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 7.** Photo taken from the northwestern location, facing Southwest. Ditch BMP has been installed but has not been stabilized. The eastern ditch BMP had check dams to stabilize the ditch BMP.



**Photo 8.** Photo taken from the northwestern location, facing South. See comments under Photo 7.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 9.** Photo taken from the western location, facing North. Appears topsoil has been stockpiled along the western perimeter of the location. All other stockpiles appeared to be left unconsolidated without any stabilization BMP.