



**Photo 1. View from the southeastern edge of the project area facing center.**



**Photo 2. View of the eastern fill slope from the southeastern edge facing northward.**



**Photo 3. View of area in the southern project area where concentrated stormwater from the well pad is causing erosion in the southern project area.**



**Photo 4. View of another area in the southern project area where concentrated flows from the well pad are eroding the southern reclamation areas.**



**Photo 5. View of sediment deposition on the well pad from the northern cut-slope.**



**Photo 6. View of erosion on the northern cut slope and sediment deposition on the well pad. Stormwater controls have not been installed.**