

Inspection Photos

Location Name: Phillips 23-42

API #: 05-123-19268

Location ID: 330547



Wellhead looking north



Stained soil under hammer union where casing ties into flowline. Wellhead packing is leaking. Change over above master valve is leaking.