

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/28/2017

Submitted Date:

11/28/2017

Document Number:

666804082

FIELD INSPECTION FORM

Loc ID 424796 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrllc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrllc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424800	WELL	PR	06/13/2012	GW	045-20942	EPPERLY 23A-23-692	PR
424802	WELL	PR	07/19/2012	GW	045-20943	EPPERLY 13D-23-692	PR
424803	WELL	PR	07/26/2012	GW	045-20944	EPPERLY 14B-23-692	PR
424807	WELL	PR	07/19/2012	GW	045-20945	EPPERLY 13C-23-692	PR
424808	WELL	PR	07/26/2012	GW	045-20946	EPPERLY 24D-23-692	PR
424809	WELL	PR	07/19/2012	GW	045-20947	EPPERLY 13A-23-692	PR
424810	WELL	PR	06/13/2012	GW	045-20948	EPPERLY 23B-23-692	PR
424811	WELL	PR	07/23/2012	GW	045-20949	EPPERLY 23D-23-692	PR
424813	WELL	PR	06/13/2012	GW	045-20950	EPPERLY 23C-23-692	PR
424815	WELL	PR	07/10/2012	GW	045-20951	EPPERLY 13B-23-692	PR
424816	WELL	PR	07/26/2012	GW	045-20952	EPPERLY 24B-23-692	PR
424932	WELL	PR	07/26/2012	GW	045-20979	Epperly 14D-23-692	PR

General Comment:

Routine inspection

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	424800	Type:	WELL	API Number:	045-20942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424802	Type:	WELL	API Number:	045-20943	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424803	Type:	WELL	API Number:	045-20944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424807	Type:	WELL	API Number:	045-20945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424808	Type:	WELL	API Number:	045-20946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424809	Type:	WELL	API Number:	045-20947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424810	Type:	WELL	API Number:	045-20948	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	424811	Type:	WELL	API Number:	045-20949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: <u>424813</u>	Type: <u>WELL</u>	API Number: <u>045-20950</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>424815</u>	Type: <u>WELL</u>	API Number: <u>045-20951</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>424816</u>	Type: <u>WELL</u>	API Number: <u>045-20952</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:
Facility ID: <u>424932</u>	Type: <u>WELL</u>	API Number: <u>045-20979</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Check Dams	Pass			
Gravel	Pass					
		Gravel	Pass			
Seeding	Pass					
Berms	Pass					
Ditches	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666804083	van	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4312032