

Inspection Photos
Location Name: Tiffany C #1
API: 05-067-06416



Stained gravel beneath prime mover on C #1.



Location of produced water release with flow paths running off of location and mixing with irrigation water.

Inspection Photos
Location Name: Tiffany C #1
API: 05-067-06416



Downstream of release area where water enters culvert.



Wet soil east of separator and meter run.

Inspection Photos
Location Name: Tiffany C #1
API: 05-067-06416



Edge of location up gradient of release area.



Release area on east edge of location. Flow paths left pad.

Inspection Photos
Location Name: Tiffany C #1
API: 05-067-06416



Stained gravel at exhaust on Tiffany #2-3.



NE anchor marker has been knocked down.