

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401445845

Date Received:

11/30/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 36200

Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO

Address: 3600 S. YOSEMITE ST - STE 900

City: DENVER State: CO Zip: 80237-1830

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

mgriggs@sierra-hamilton.com

ecooper@sierra-hamilton.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102291

Inspection Date: 09/26/2017

FIR Submit Date: 10/11/2017

FIR Status: _____

Inspected Operator Information:

Company Name: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO

Company Number: 36200

Address: 3600 S. YOSEMITE ST - STE 900

City: DENVER State: CO Zip: 80237-1830

LOCATION - Location ID: 312854

Location Name: CHIVINGTON-612N97W Number: 20SESE County: MOFFAT

Qtrqr: SESE Sec: 20 Twp: 12N Range: 97W Meridian: 6

Latitude: 40.980277 Longitude: -108.308690

FACILITY - API Number: 05-081- -00 Facility ID: 222617

Facility Name: CHIVINGTON Number: 1

Qtrqr: SESE Sec: 20 Twp: 12N Range: 97W Meridian: 6

Latitude: 40.980277 Longitude: -108.308690

CORRECTIVE ACTIONS:

1 CA# 104787

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details. Install BMPs to control, diffuse SW energy, soil migration On & Off site, and generally stabilize Location.

Date: 11/01/2017

Response: CA COMPLETED

Date of Completion: 11/28/2017

Corrective actions have been completed. Topsoil has been applied to location and access road. both areas have been ripped/graded to stabilize the soil. Part of the silt fence has been removed and been replaced with rip rap to

Operator Comment: diffuse water run on. Drainage swales have been constructed on both the east and west sides of the location, with check dams installed to divert and diffuse run on. The area has been seeded. Sheep are currently residing in the enclosed fenced area. Their waste material will be helpful to establish future plant growth. The sheep will be removed after a number of days. Run on has been either diverted or diffused. Run off has been diffused.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mary Griggs

Signed: _____

Title: Director for Reciever

Date: 11/30/2017 1:50:44 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401472656	Reclamation photo
401472658	Reclamation photo
401472662	Reclamation photo
401472668	Reclamation photo
401472672	Reclamation photo
401472673	Reclamation Photo
401472675	Reclamation photo
401472678	Reclamation photo

Total Attach: 8 Files