

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2017

Submitted Date:

12/01/2017

Document Number:

679700678

FIELD INSPECTION FORM

Loc ID 329266 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	
Greg Becker		gregory.becker@greeleygov.c om	Greeley Fire Department
Axelson, John		john.axelson@state.co.us	COGCC East Environmental Supervisor
MacLaren, Joe		joe.maclaren@state.co.us	COGCC Engineering Integrity Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249282	WELL	SI	04/01/2017	OW	123-17084	MCINTYRE 34-16	EI
453260	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

General Comment:

[COGCC Environmental Staff Inspection in response to suspected release of E&P Waste in Rover Run Dog Park](#)

Inspected Facilities

Facility ID: 249282 Type: WELL API Number: 123-17084 Status: SI Insp. Status: EI

Facility ID: 453260 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC Environmental Staff responded to the City of Greeley Rover Run Dog Park to investigate a suspected release of E&P Waste from an abandoned flowline. COGCC Environmental Staff met onsite with the City of Greeley Fire Department Personnel. Fire Department Personnel advised COGCC that a citizen had contacted the City of Greeley park staff on 11/21/2017 to report oil bubbling from the ground. Park staff were unable to locate the incident until the citizen reported the oil bubbling again on 11/29/2017 and park staff located the area of concern. SRC Energy agreed to excavate the area and reportedly completed the excavation on the morning of 11/30/2017. Greeley Fire Department contacted COGCC and COGCC personnel arrived onsite 11/30/2017 and observed an area that was recently excavated and backfilled with clean material. Oil impacted soil remained on the surface in the area of the excavation. COGCC contacted Noble Energy who indicated they would be responsible for remediation of the flowline release. Noble indicated that utility locates had been requested and excavation to investigate and remediate the release would commence on 12/5/2017.

Corrective Action:

Operator has submitted Form 19 Initial Report. Form 19 Supplemental Report is due 12/9/2017.

Date: 12/09/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700680	Photo of Release Area 11-30-2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314957