



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern cut-slope from the northern edge facing northwestward. Rilling and sediment deposition are occurring within the slope. Slope stabilization and erosion control measures are needed here.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and dropseed (*Sporobolus* sp.)





Photo 4. View of an erosional channel approximately 2.5 feet wide and deep in the western portion of the project area.



Photo 5. View of area along the northern access road where concentrated stormwater flows are eroding the roadside and result in in sediment loss.