

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2017

Submitted Date:

12/04/2017

Document Number:

684904741**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
452048 _____ Pesicka, Conor _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10518
 Name of Operator: CONFLUENCE DJ LLC
 Address: 1001 17TH STREET #1250
 City: DENVER State: CO Zip: 80202

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dickinson, Mike		mdickinson@confluencelp.com	Sr. VP of Operations
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452352	WELL	DG	11/01/2017		123-45542	Buford 33-10-4L	AO
452354	WELL	DG	11/02/2017		123-45544	Buford 33-9-3L	AO

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound mitigation on W, S sides		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 452352 Type: WELL API Number: 123-45542 Status: DG Insp. Status: AO

Complaint

Comment: [Complaint #: 200444626](#)
[Field Inspector Assigned: C Pesicka](#)
[Well Number: 05- Location #: 452048](#)
[Inspection Document #: 684904741](#)
 Nature of complaint: Sound, Odor
 If Sound GPS Coordinates of Survey Location: n/a
 Inspection Observations:
 An inspection of the above site was conducted with a focus on sound and odor. The operator undertook a sound mitigation study and implemented items to mitigate sound, constructing barriers on the west and south side of location. No odor was detected off location.
[18A doc#: 200444740](#)

Corrective Action: _____ Date: _____

Facility ID: 452354 Type: WELL API Number: 123-45544 Status: DG Insp. Status: AO

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Ditches	Pass					
Waddles	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684904742	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4316471