

COGCC conducted an inspection of the Owl Creek State 10-16 location (Location ID 332045) on November 16, 2017 (Document 684904715). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater channeling from W to E through center of location. Install or repair required BMPs per Rule 1002.f.

Response: Noble has filled and repaired the observed erosion.

Name: Owl Creek State 10-16

Location ID: 332045

COGCC conducted an inspection of the Owl Creek State 10-16 location (Location ID 332045) on November 16, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater channeling from W to E through center of location. Install or repair required BMPs per Rule 1002.f.

COGCC – 11/16/17



Photo 1: Location, looking SE

Noble Energy – 11/21/17



Photo NBL1. Location, looking SE.

Name: Owl Creek State 10-16

Location ID: 332045

COGCC conducted an inspection of the Owl Creek State 10-16 location (Location ID 332045) on November 16, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater channeling from W to E through center of location. Install or repair required BMPs per Rule 1002.f.

COGCC – 11/16/17



Photo 3: Stormwater channeling, looking W

Noble Energy – 11/21/17



Photo NBL2. Erosion/channeling filled, looking W.

Name Owl Creek State 10-16

Location ID: 332045

COGCC conducted an inspection of the Owl Creek State 10-16 location (Location ID 332045) on November 16, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

1. Storm Water: Stormwater channeling from W to E through center of location. Install or repair required BMPs per Rule 1002.f.

COGCC – 11/16/17



Photo 4: Stormwater channeling, looking E

Noble Energy – 11/21/17



Photo NBL3. Erosion/channeling was repaired, looking E.