

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2017

Submitted Date:

12/05/2017

Document Number:

685304008**FIELD INSPECTION FORM**Loc ID 325244 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7650Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATIONAddress: 4900 COLLEGE BLVDCity: FARMINGTON State: NM Zip: 87402**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|----------------------------|---------|
| Stradling, Zak | (505) 324-5074 | zstradling@bmgdrilling.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214390 | WELL | SI | 05/26/2009 | GW | 067-05805 | LA PLATA 1 | SI |

General Comment:[Inspection conducted as part of witnessing plug and abandonment of the La Plata 1.](#)[See link at end of report for path to completed inspection pictures.](#)[Work is being completed by A Plus Well Service using Rig A - 7.](#)

Location**Lease Road:**

| | | | |
|-------------------|---|-------|--|
| Type | Access | | |
| comment: | Dirt and gravel access road. Road is rutted and rough. Road is passable and will be reclaimed after well plugging is completed. | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | WELLHEAD | | |
| Comment: | Framed metal sign located at entrance to location. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|---|-------|--|
| Comment: | Operator contact information posted on wellhead sign. | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------|-----------|-------|-----------------|
| | | | corrective date |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|----------------|----------|------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 0 | | | | |
| Comment: | Tanks removed. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |

Inspected FacilitiesFacility ID: 214390 Type: WELL API Number: 067-05805 Status: SI Insp. Status: SI**Cement**Cement ContractorContractor Name: A Plus Well ServiceContractor Phone: 505-325-2627Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Plugging is being completed by A Plus Well Service Rig A-7.
 Bradenhead test completed.
 Rig and equipment set up on well. Water pumped down hole to kill well. Trip 1 joint of tubing out of well.
 Start tripping tubing string into well.
 SDFN.

Corrective Action: _____

Date: _____

BradenHead

Comment: Casing pressure - 530 psi. Tubing - 530 psi. Bradenhead pressure - 85 psi.
 Bradenhead valve was opened and blew down in 2 mins.
 Casing valve was opened and was blown down. Casing continued to flow gas at approximately 15 psi.
 Bradenhead pressure - 5 min - 0 psi, 10 min - 0 psi, 15 - 0 psi, 20 min - 0 psi, 25 min - 0 psi, 30 min - 0 psi.
 Casing pressure - Casing continued to flow at approximately 10 - 15 psi.
 Instantaneous Bradenhead pressure - 0 psi.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location on ridgeline surrounded by dry land forest area. Juniper and Pinion Pines are primary surrounding trees. Sage Brush and grasses make up bulk of primary surround vegetation.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Compaction | Pass | | | |
| Compaction | Pass | Ditches | Pass | | | |

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 685304027 | Completed inspection pictures. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318213 |