

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/28/2017

Submitted Date:

12/05/2017

Document Number:

685304014

FIELD INSPECTION FORM

Loc ID 325244 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214390	WELL	SI	05/26/2009	GW	067-05805	LA PLATA 1	SI

General Comment:

Inspection completed as part of witnessing of plugging operation on the La Plata 1 well.
See link at end of report for path to completed inspection pictures.
Work is being completed by A Plus Well Service Rig A-7.

Location

Lease Road:

Type	Access		
comment:	Dirt and gravel access road. Rutted and rough. Road will be reclaimed after well is plugged.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Framed metal sign at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			
In Containment:	No				
Comment:	<input style="width: 100%;" type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					

Equipment:

	#		corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:		Date:			

Paint

Condition	<input style="width: 85%;" type="text"/>
Other (Content)	<input style="width: 100%;" type="text"/>
Other (Capacity)	<input style="width: 100%;" type="text"/>
Other (Type)	<input style="width: 100%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214390 Type: WELL API Number: 067-05805 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: A Plus Well Service

Contractor Phone: 505-325-2627

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Start of day casing pressure - 500 psi, bradenhead pressure - 75 psi.
 Blew bradenhead down in under 2 mins. Blew casing down and pump water to kill well.
 Trip tubing into well to tag TD at 8058'. Tubing bottomed at 5805'. Investigation reveals that well was reentered and TD is now 5800'. After consultation with SW Engineer Mark Weems determination was made to change procedure and skip plug #1 and move to plug #2 and continue as written.
 Crew starts tripping tubing out of well and set up for plug #2. SDFN.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304028	Completed inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318214