

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2017

Submitted Date:

12/05/2017

Document Number:

679700682**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
319453 _____ ALLISON, RICK _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@syrginfo.com	All Synergy Inspections

General Comment:

COGCC Environmental Staff Inspection in response to release on Noble McIntyre 34-16 flowline in adjacent dog park. A small pothole is present near separator where Operator exposed capped McIntyre flowline to perform locates. Site is not in mapped 100-year floodplain (FEMA).

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700684	Bunn M 1-34 production facility photos 12-5-17	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318589